Late Representations – 26th October 2023

FILE REF.	SITE AND DETAILS	PAGE NO.
SMD/2019/0646	Moneystone Quarry (Reserved Matters)	3-66
	Additional Officer Recommendation 1.That Condition 5 specify natural timber cladding for the elevations of the lodges for the avoidance of any doubt	
	2. That Condition 25 (Bridge) also include for additional landscaping picking up advice from the Trees and Woodland Officer in his response dated 22/6/22	
	3. Additional condition to secure means of enclosure to the gas compound	
	Churnet Valley Conservation Society Five further letters of objection have been received from the Churnet valley Conservation Society raising the following additional points: • Quarry 3 has been re designated as a reservoir. There is a requirement for LPAs to discuss their proposed site allocations with reservoir undertakers to: a)avoid an intensification of development within areas at risk from reservoir failure; and b)ensure that reservoir undertakers can assess the cost implications of any reservoir safety improvements required due to changes in land use downstream of their assets. There is also a requirement for the owner/operator to have a Flood plan. No evidence is available that one is available • There is one very significant omission that, in the interest of balance and fairness, should be inserted in the introductory section of your report, (p 3 and 4) where you summarise the salient history of the application for the outline permission. You mention the approval of application SMD/2016/0378 but unfortunately you have omitted to mention at this point the refusal of the full, no right turn application SMD/2016/0388 by the Council at the same meeting. This is a serious omission in that its absence could lead the PAC members to be misinformed of the reality of what actually happened at the same meeting where the access in the outline approval (SMD/2016/0378) was given, but then, promptly 20 minutes later, was removed by the PAC's refusal of the full permission on the grounds of road safety. • Nothing has been done to address contamination concerns of the EA at the outline stage. No remedial work or monitoring of the site has taken place	
	There is no evidence on file of the Council questioning	

FILE REF.	SITE AND DETAILS	PAGE NO.
	the authority and appropriateness of the JBA expert	
	hydrology report	
	Quarry 3 does not represent limited sensitive	
	development	
	 Few new jobs to be created. The need for independent scrutiny of the controlled water 	
	before the hearing is essential. It has not been produced because you have neglected the problem for too long and now you cannot be said to have	
	considered it properly when weighing the planning balance in order to compile your report to the PAC.	
	There is no evidence of nay reports on safety issues at	
	the quarry that the applicant and its agent maintain have beeb carried out on a monthly basis by way of their re	
	assuring public concerns (e-mail 19 th Sept 2023)	
	 In 2016 SCC had to issue a stopping order to prevent illicit dumping including that of toxic waste material in 	
	quarry 2	
	by its agents Genesis and other associates like T W Frizell.	
	 Since 2014 Laver Leisure has also allowed the illegal use of the quarry buildings as premises for an unauthorised 	
	scrap metal business despite	
	continuous threats of enforcement by SCC.	
	•Car share proposals are impractical as singleton car use will	
	undoubtedly prevail. •Public transport to the site is no longer available.	
	Poor specification for lodges. Not comparable to Centre Parcs	
	or today's expectations of luxury.	
	•Potential for 100% private ownership of lodges, consistent with	
	all other Laver Leisure sites	
	•Lodges over water, danger from falls from decking.	
	•Cold water shock kills swimmers/ and fallers.	
	•Compromised safety, with a very deep lake in quarry 3 with	
	deep water benches that will create difficulties climbing out of the cold water.	
	•Only a single access road available for emergency services into	
	such a large 'conurbation'.	
	•No plan at all to deal with unstable fill in Quarry 2 to protect	
	hliday makers.	
	•There have been historic landslides. Slope and spillway/outfall	
	instability due to reduced strength of wet rock.	
	•Rock falls protection design parameters or their location(s) to prevent over topping of lake in quarry 3 due to rock falls have	
	not been adequately provisioned in 0646.	
	•Lack of consultation with emergency services.	
	•Inadequate, time expired Environmental Impact Assessments.	

FILE REF.	SITE AND DETAILS	PAGE NO.
	 Increased water flow will potentially damage SSSI. Inadequate search for and assessment of Historic Assets. Inadequate wildlife and landscape assessments for vulnerable species. 	
	 Ignoring SMDC PAC decision to refuse (SMD/2016/0388) the requested no-right-turn out of Moneystone Park onto Eaves Lane. No statement regarding Sat-Nav directions from (and to) Alton Towers from Moneystone Park. Inadequate sports and leisure facilities for the number of visitors the site is intended for. 	
	 Major deviation from both the Churnet Valley Masterplan and the outline planning permission. Does not meet SMDC's own policies for reducing global warming impact. 	
	 41 further letters of Objections received since the report was written – summarised as follows:- Unlawful waste is buried at the quarry. The Council is required to abide by the Statement of Community involvement. It has not done so. Noise Pollution 	
	 Loss of biodiversity and harm to the environment instability of the ground Concerned about the safety of reservoir in quarry 3 due to no overflow system Concerned that the development would expose a carcinogenic risk from disturbance of the silica sand Access and traffic – particularly the Eaves Lane/A52 Junction 	
	 Strain on local services and infrastructure due to private ownership of lodges Concerns regarding drainage of the site in relation to the Churnet River and silica sand deposits Concerns with competing with local businesses Concerns about subsidence Concerns about safe working practices Concerns about road safety on Farley Road 	
	 Concerns that car reliance is at odds with SMDC policy to reduce CO2 emissions Concerns about tsunamis Concerns about the stability of jobs created 	

FILE REF.	SITE AND DETAILS	PAGE NO.
	 Concerns that the development goes against Policy SS1 locally distinctive Concerns about capacity of local sewers Concerns regarding impact on local SSSI's and Ancient Woodland Lack of EV charging points and green energy No public transport to the site Concerns about flooding Concerns the development does not conform with SMDC Policy SS11 – scale, design, quality Concerns the development does not conform with SMDC Policy E4 – Scale, character Concerns the development does not conform with SMDC Policy DC1 - high-quality, add value Concerns about general safety in a disused quarry Unsustainable development 	
SMD/2019/0716	Moneystone Quarry (Retention and change of use of lab building) Churnet Valley Conservation Society Five further letters of objection have been received from the Churnet valley Conservation Society raising the following additional points: Quarry 3 has been re designated as a reservoir. There is a requirement for LPAs to discuss their proposed site allocations with reservoir undertakers to: a) avoid an intensification of development within areas at risk from reservoir failure; and b) ensure that reservoir undertakers can assess the cost implications of any reservoir safety improvements required due to changes in land use downstream of their assets. There is also a requirement for the owner/operator to have a Flood plan. No evidence is available that one is available Nothing has been done to address contamination concerns of the EA at the outline stage. No remedial work or monitoring of the site has taken place There is no evidence on file of the Council questioning the authority and appropriateness of the JBA expert hydrology report Quarry 3 does not represent limited sensitive development	67-88

FILE REF.	SITE AND DETAILS	PAGE NO.
	 Few new jobs to be created. The need for independent scrutiny of the controlled water before the hearing is essential. It has not been produced because you have neglected the problem for too long and now you cannot be said to have considered it properly when weighing the planning balance in order to compile your report to the PAC. There is no evidence of nay reports on safety issues at the quarry that the applicant and its agent maintain have beeb carried out on a monthly basis by way of their re assuring public concerns (e-mail 19th Sept 2023) In 2016 SCC had to issue a stopping order to prevent illicit dumping including that of toxic waste material in quarry 2 by its agents Genesis and other associates like T W Frizell. Since 2014 Laver Leisure has also allowed the illegal use of the quarry buildings as premises for an unauthorised scrap metal business despite 	
	There is one very significant omission that, in the interest of balance and fairness, should be inserted In the introductory section of your report, (p 3 and 4) where you summarise the salient history of the application for the outline permission. You mention the approval of application SMD/2016/0378 but unfortunately you have omitted to mention at this point the refusal of the full, no right turn application SMD/2016/0388 by the Council at the same meeting. This is a serious omission in that its absence could lead the PAC members to be misinformed of the reality of what actually happened at the same meeting where the access in the outline approval (SMD/2016/0378) was given, but then, promptly 20 minutes later, was removed by the PAC's refusal of the full permission on the grounds of road safety.	
	 Continuous threats of enforcement by SCC. Car share proposals are impractical as singleton car use will undoubtedly prevail. Public transport to the site is no longer available. Poor specification for lodges. Not comparable to Centre Parcs or today's expectations of luxury. Potential for 100% private ownership of lodges, consistent with all other Laver Leisure sites Lodges over water, danger from falls from decking. Cold water shock kills swimmers/ and fallers. Compromised safety, with a very deep lake in quarry 3 with 	

FILE REF.	SITE AND DETAILS	PAGE NO.
	deep water benches that will create difficulties climbing out of the cold water.	
	•Only a single access road available for emergency services into such a large 'conurbation'.	
	•No plan at all to deal with unstable fill in Quarry 2 to protect hliday makers.	
	•There have been historic landslides. Slope and spillway/outfall	
	instability due to reduced strength of wet rock. •Rock falls protection design parameters or their location(s) to prevent over topping of lake in quarry 3 due to rock falls have not been adequately provisioned in 0646.	
	Lack of consultation with emergency services. Inadequate, time expired Environmental Impact Assessments. Increased water flow will potentially damage SSSI.	
	 Inadequate search for and assessment of Historic Assets. Inadequate wildlife and landscape assessments for vulnerable species. 	
	•Ignoring SMDC PAC decision to refuse (SMD/2016/0388) the requested no-right-turn out of Moneystone Park onto Eaves Lane.	
	•No statement regarding Sat-Nav directions from (and to) Alton Towers from Moneystone Park.	
	•Inadequate sports and leisure facilities for the number of visitors the site is intended for.	
	•Major deviation from both the Churnet Valley Masterplan and the outline planning permission.	
	•Does not meet SMDC's own policies for reducing global warming impact.	
	8 Further letters of Objections received since the report was written – summarised as follows:-	
	Unlawful waste is buried at the quarry.	
	 The Council is required to abide by the Statement of Community involvement. It has not done so. 	
	• Noise	
	PollutionLoss of biodiversity and harm to the environment	
	 instability of the ground 	
	Concerned about the safety of reservoir in quarry 3 due	
	to no overflow systemConcerned that the development would expose a	
	carcinogenic risk from disturbance of the silica sand	
	 Access and traffic – particularly the Eaves Lane/A52 Junction 	
	Strain on local services and infrastructure due to private ownership of lodges	

FILE REF.	SITE AND DETAILS	PAGE NO.
	 Concerns regarding drainage of the site in relation to the Churnet River and silica sand deposits Concerns with competing with local businesses Concerns about subsidence Concerns about safe working practices Concerns about road safety on Farley Road Concerns that car reliance is at odds with SMDC policy to reduce CO2 emissions Concerns about tsunamis Concerns about the stability of jobs created Concerns that the development goes against Policy SS1 – locally distinctive Concerns about capacity of local sewers Concerns regarding impact on local SSSI's and Ancient Woodland Lack of EV charging points and green energy No public transport to the site Concerns about flooding Concerns the development does not conform with SMDC Policy SS11 – scale, design, quality Concerns the development does not conform with SMDC Policy E4 – Scale, character Concerns the development does not conform with SMDC Policy DC1 - high-quality, add value Concerns about general safety in a disused quarry Unsustainable development The current application has ignored SMD/2016/0388. This application effectively encourages law breaking and therefore 0646 should refused until a sensible and safe access arrangement is brought forward and decided upon 	
SMD/2022/0014	Moneystone Quarry (Surface water outfall) Churnet Valley Conservation Society Five further letters of objection have been received from the Churnet valley Conservation Society raising the following additional points: Quarry 3 has been re designated as a reservoir. There is	89- 108
	a requirement for LPAs to discuss their proposed site	

FILE REF.	SITE AND DETAILS	PAGE NO.
FILE REF.	allocations with reservoir undertakers to: a) avoid an intensification of development within areas at risk from reservoir failure; and b) ensure that reservoir undertakers can assess the cost implications of any reservoir safety improvements required due to changes in land use downstream of their assets. There is also a requirement for the owner/operator to have a Flood plan. No evidence is available that one is available • Nothing has been done to address contamination concerns of the EA at the outline stage. No remedial work or monitoring of the site has taken place • There is no evidence on file of the Council questioning the authority and appropriateness of the JBA expert hydrology report • Quarry 3 does not represent limited sensitive development • Few new jobs to be created. • The need for independent scrutiny of the controlled water before the hearing is essential. It has not been produced because you have neglected the problem for too long and now you cannot be said to have considered it properly when weighing the planning balance in order to compile your report to the PAC. • There is no evidence of nay reports on safety issues at the quarry that the applicant and its agent maintain have beeb carried out on a monthly basis by way of their re assuring public concerns (e-mail 19 th Sept 2023) • In 2016 SCC had to issue a stopping order to prevent illicit dumping including that of toxic waste material in quarry 2 by its agents Genesis and other associates like T W Frizell. • Since 2014 Laver Leisure has also allowed the illegal use of the quarry buildings as premises for an unauthorised scrap metal business despite • continuous threats of enforcement by SCC. •Car share proposals are impractical as singleton car use will undoubtedly prevail. •Public transport to the site is no longer available.	

FILE REF.	SITE AND DETAILS	PAGE NO.
	the cold water. Only a single access road available for emergency services into such a large 'conurbation'. No plan at all to deal with unstable fill in Quarry 2 to protect hliday makers. There have been historic landslides. Slope and spillway/outfall instability that the standard standard for the standard spillway.	
	instability due to reduced strength of wet rock. •Rock falls protection design parameters or their location(s) to prevent over topping of lake in quarry 3 due to rock falls have not been adequately provisioned in 0646. •Lack of consultation with emergency services.	
	 Inadequate, time expired Environmental Impact Assessments. Increased water flow will potentially damage SSSI. Inadequate search for and assessment of Historic Assets. Inadequate wildlife and landscape assessments for vulnerable 	
	species. •Ignoring SMDC PAC decision to refuse (SMD/2016/0388) the requested no-right-turn out of Moneystone Park onto Eaves Lane.	
	 No statement regarding Sat-Nav directions from (and to) Alton Towers from Moneystone Park. Inadequate sports and leisure facilities for the number of visitors the site is intended for. Major deviation from both the Churnet Valley Masterplan and 	
	the outline planning permission. •Does not meet SMDC's own policies for reducing global warming impact.	
	22 further letters of Objections received since the report was written – summarised as follows:-	
	 Unlawful waste is buried at the quarry. The Council is required to abide by the Statement of Community involvement. It has not done so. Noise 	
	 Pollution Loss of biodiversity and harm to the environment instability of the ground 	
	 Concerned about the safety of reservoir in quarry 3 due to no overflow system Concerned that the development would expose a 	
	 carcinogenic risk from disturbance of the silica sand Access and traffic – particularly the Eaves Lane/A52 Junction 	
	 Strain on local services and infrastructure due to private ownership of lodges Concerns regarding drainage of the site in relation to the 	

Churnet River and silica sand deposits Concerns with competing with local businesses Concerns about subsidence Concerns about safe working practices Concerns about road safety on Farley Road Concerns that car reliance is at odds with SMDC policy to reduce CO2 emissions Concerns about tsunamis Concerns about tsunamis Concerns that the development goes against Policy SS1 – locally distinctive Concerns about capacity of local sewers Concerns regarding impact on local SSSI's and Ancient Woodland Lack of EV charging points and green energy No public transport to the site Concerns the development does not conform with SMDC Policy SS11 – scale, design, quality Concerns the development does not conform with SMDC Policy E4 – Scale, character Concerns the development does not conform with SMDC	FILE REF.	SITE AND DETAILS	PAGE NO.
Concerns about general safety in a disused quarry Unsustainable development		 Concerns with competing with local businesses Concerns about subsidence Concerns about safe working practices Concerns about road safety on Farley Road Concerns that car reliance is at odds with SMDC policy to reduce CO2 emissions Concerns about tsunamis Concerns about the stability of jobs created Concerns that the development goes against Policy SS1 – locally distinctive Concerns about capacity of local sewers Concerns regarding impact on local SSSI's and Ancient Woodland Lack of EV charging points and green energy No public transport to the site Concerns about flooding Concerns the development does not conform with SMDC Policy SS11 – scale, design, quality Concerns the development does not conform with SMDC Policy E4 – Scale, character Concerns the development does not conform with SMDC Policy DC1 - high-quality, add value Concerns about general safety in a disused quarry 	